

CONTROLS AND DISPLAYS

PLSS

Instruction Labels

Manual Controls

Feedwater Shutoff Valve

O₂ Shutoff Valve

H₂O Diverter Valve

Auxiliary Feedwater Shutoff Valve

Gas Trap

PLSS Straps (with 1 inch standoffs)

Umbilicals

O₂ Inlet

O₂ Outlet

H₂O

Electrical (to PGA)

Battery

RCU

Antenna (from OPS)

Connector Covers

Hose Routing

Battery Locking Mechanism

Battery

LiOH Canister Cover

LiOH Cartridge

LiOH Cartridge and Container Assembly

Instruction Decal

Green Δ P Indicator Pin

Temperature Decal

Expendable Number

Recharge Connectors

H₂O Fill

H₂O Drain

Primary H₂O Vent

Auxiliary H₂O Vent

(Sight Glasses)

RCU

PGA Mounting Mechanism

Lower PGA Mounting Hook

OPS Actuator Mounting Bracket

Mode Selector Switch

